FREENOVE ESP32-S3 WROOM Pinout

PWD	Power
GND	Ground
Serial	Serial for Debugging/Programming
ADCX_CH	Analog-to-Digital Converter
RESET	Reset the chip
GPIOX	GPIO Input and Output
TOUCHX	Touch Sensor Input Channel
STRAP	Strapping Pin Functions
SD	On-board SD Card Pin
LED	On-board LED Pin
WS2812	On-board WS2812 Pin
PSRAM	Built-in expansion memory chip pin
USB	USB Function Pin
CAMERA	Camera Pin
JTAG	Jtag for Debugging
~/\~	PWM Capable Pin